Tuesday, June 25 2002

STS-107 launch delayed

ASA managers suspended STS-107 launch preparations for Space Shuttle Columbia on Monday. The launch was previously scheduled for July 19. The delay is due to several small cracks found in metal liners used to direct the flow inside main propulsion system propellant lines on other orbiters in the fleet. Inspections of Columbia's flow liners are part of an intensive analysis of the cracks found on Space Shuttle Atlantis and Space Shuttle Discovery. The impact of the investigation on other upcoming Space Shuttle launches has not been determined.

Air outage in Bldg. 4200 at 6 p.m. Tuesday and all day Saturday

Marshall cafeterias in Bldg. 4610, 4203 and 4471 and Charlie's Grill in Bldg. 4200 closed July 5

Wellness Center ribbon cutting ceremonies Thursday

All Marshall team members are invited to the grand opening and ribbon cutting ceremonies. Thursday at the Wellness Center, Bldg. 4315. The event begins at 10 a.m. The Wellness Center features state-of-the art exercise equipment, 44 pieces of cardio equipment including 15 treadmills, new wood floors for the racquetball and basketball courts, aerobics classes, yoga, kick boxing and new air conditioning.

http://inside.msfc.nasa.gov